Installation   BRIDGE

- Mount power supply to a 4" x 4" square junction box (through a 1/2" knockout)
- Connect the supply's class 1 line voltage wires
- Mount Bridge unit to top of same junction box
- Connect the power supply's class 2 low voltage wires to the Bridge's terminal connectors. Unit's LEDs will flash indicating power up
- Attach CAT-5 cables from lighting zones to the appropriate Bridge RJ-45 ports according to system design
- Fill out Bridge's port identification sticker(s) and commissioning card

N | **H**
BLK - 120 V
ORN - 277

WHT

RED   PS150

BLK   BLK/ORN

Commisioning Card

Serial # _____

1 _____   8 _____
2 _____   7 _____
3 _____   6 _____
4 _____   5 _____