
# **Wire Termination**

## **Grounding Accessories**


- Solid and stranded pigtail lead wires are convenient for stranded device grounding applications
- Grounding screws offer a unique thread-forming feature, plus combination hex, Phillips, slotted and Robertson tip

### **Grounding Tails - Stranded Wire**




Stranded Wire Grounding Tails	Quantity	Cat. No.	Fig.
14 AWG stranded 7-3/4 in. tail w/#10 fork & 10 ring and ground screw	Bag of 25	30-3183	Α
12 AWG stranded, 7-3/4 in. tail w/#10 fork & 10 ring and ground screw	Bag of 25	30-3184	В
12 AWG stranded, 7-3/4 in. tail w/#10 fork & 10 ring and ground screw	Bundle of 100	30-3284	В
12 AWG stranded, 2-wire tail joined w/#10 ring and ground screw, one stripped-end tail and one 10 fork tail	Bag of 25	30-3287	С
12 AWG stranded, 2-wire tail joined w/#10 ring and ground screw and two #10 fork tails	Bag of 25	30-3288	D
12 AWG stranded, 3-wire tail joined w/#10 ring and ground screw, one stripped-end tail and two 10 fork tails	Bag of 25	30-3289	E

### **Grounding Tails - Solid Wire**



Solid Wire Grounding Tails	Quantity	Cat. No.	Fig.
14 AWG solid, 8 in. tail w/loop & ground screw and stripped end	Box of 50	30-3390	А
12 AWG solid, 8 in. tail w/loop & ground screw and stripped end	Box of 50	30-3392	В
12 AWG solid, 8 in. tail w/loop & ground screw and stripped end	Bundle of 50	30-3496	В
12 AWG solid, 10 in. tail w/loop & ground screw and stripped end	Bundle of 50	30-3394	С

### **Grounding Accessories**





Miscellaneous Grounding Products	Quantity	Cat. No.	Fig.
Ground Screw, thread-forming, combination hex, Phillips, slotted and Robertson-tip	Pack of 50	30-3194	А
Ground Screw, thread-forming, combination hex, Phillips, slotted and Robertson-tip	Bag of 100	30-3294	А
Grounding clip – accepts 10, 12 or 14 AWG wire	Pack of 100	30-3395	В

